

Fig 1




Fig 2

2/12









Fig 3













dist = 0.004 rad t = 1.34 ms Loss = 0.33 mJ





7/12






Fig 11c

9/1Z



dist = 0.200 rad t = 4.33 ms Loss = 41.89 mJ

10/12




dist = 0.200 rad

t = 4.5ms

Loss = 3.2mJ

11/12



dist = 0.004 rad t = 0.89ms Loss = 0.31mJ




Fig 16